




| Sr.No. | Part No.    | Part Name                                             | Qty. |
|--------|-------------|-------------------------------------------------------|------|
| 1      | C8145.01.04 | Swivel Washer                                         | 1    |
| 2      | C8145.01.03 | Swivel Hexnut                                         | 1    |
| 3      | C8145.01.05 | Swivel Sleeve                                         | 2    |
| 4      | C753.04     | O-Ring For Quick Disconnect                           | 1    |
| 5      | C8137       | Cold Index (Blue)                                     | 1    |
| 6      | C8135       | Lever                                                 | 2    |
| 7      | C8138       | Spindle Assembly Cold (LH)                            | 1    |
| 8      | C8121       | 1/2" NPT Female Eccentric Flange assembly with washer | 2    |
| 9      | C8134       | Spindle Assembly Hot (RH)                             | 1    |
| 10     | C8136       | Hot Index (Red)                                       | 1    |
| 11     | C8139       | Oval ( Raised Head) Nylock Screw for Handle           | 2    |
| 12     | C8506.51    | 2.20 GPM Aerator Holder Sub-Assembly                  | 1    |
| 13     | C8506.03    | Adapter                                               | 1    |
| 14     | C8145.02.02 | Spout Washer                                          | 1    |

